


NOTE: SHUNTING NECK INTO USE 26-04-1942.
 21 POINTS ALTERED (FORMERLY TRAP) & ADDITIONAL
 DISCS PROVIDED. SILO SIDING & G.F. "B" ADDED
 28-01-1943.

© George Pryer

ANDOVER JCN. "B" (1950)



B.R. (S) 3-POSITION BLOCK TO "A"
 BOX ON MAIN LINES. PREECE 1-WIRE
 TO "A" BOX ON NO 1 BRANCH.
 TYER'S NO 6 TABLET TO RED POST JC.
 ON BRANCH. PREECE 3-WIRE ON MAIN.
 ILLUMINATED DIAGRAM

© George Pryer
 Used with permission
 Zena Pryer - 2020

GROUND FRAME
 "B"
 NUMBERS THUS:-
 ①

GROUND FRAME
 "A"
 NUMBERS THUS:-
 ①

DETECTS HAND POINTS
 "X" IN POSITION INDICATED.

SPARE: |A:

22-09-1968 :- UP THRO' ABOLISHED AND BLOCK WORKING ON NO 1 BRANCH
 DISCONTINUED. POINTS 24 A CLIPPED "REVERSE" SIGNALS 38
 & 45 REMOVED. UP DISTANT FIXED AT CAUTION.

ALTERATIONS 28-07-1971:- FOLLOWING ABOLISHED.
 7, 22, 18 (BOTH), 11 PUSH, 27, 28, 31, 41. LEVERS 17
 18 & 19 BECAME RELEASES FOR 11 PULL, 35, 36, OR 42

Box CLOSED 02-12-1973.